

Section A-A

see Table 4.5

1' or 2' rock thickness

NOT TO SCALE



filter fabric liner

under rock

Figure II-4.9. Pipe/Culvert Outfall Discharge Protection